

INTERNATIONAL STANDARD

ISO
7503-2

First edition
1988-08-01



INTERNATIONAL ORGANIZATION FOR STANDARDIZATION
ORGANISATION INTERNATIONALE DE NORMALISATION
МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ

Evaluation of surface contamination —

Part 2 : Tritium surface contamination

Évaluation de la contamination de surface —

Partie 2: Contamination de surface par le tritium

STANDARDSISO.COM : Click to view the full PDF of ISO 7503-2:1988

Reference number
ISO 7503-2: 1988 (E)

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

Draft International Standards adopted by the technical committees are circulated to the member bodies for approval before their acceptance as International Standards by the ISO Council. They are approved in accordance with ISO procedures requiring at least 75 % approval by the member bodies voting.

International Standard ISO 7503-2 was prepared by Technical Committee ISO/TC 85, *Nuclear energy*.

Users should note that all International Standards undergo revision from time to time and that any reference made herein to any other International Standard implies its latest edition, unless otherwise stated.

Contents

	Page
1 Scope and field of application	1
2 Definitions	1
3 Method for evaluating surface contamination	1
4 Recording of contamination measurements	3
Bibliography	4

STANDARDSISO.COM : Click to view the full PDF of ISO 7503-2:1988

This page intentionally left blank

STANDARDSISO.COM : Click to view the full PDF of ISO 7503-2:1988

Evaluation of surface contamination —

Part 2 : Tritium surface contamination

1 Scope and field of application

This part of ISO 7503 applies to the evaluation of tritium contamination on surfaces of equipment and facilities, containers of radioactive materials and sealed sources.

It does not apply to the evaluation of tritium contamination of the skin and of clothing.

NOTE — Evaluation of surface contamination from beta-emitters (maximum beta energy greater than 0,15 MeV) and alpha-emitters is dealt with in ISO 7503-1. Other radionuclides of practical importance (for example electron capture and isomeric transition emitters) will be dealt with in a future International Standard.

2 Definitions

For the purposes of this part of ISO 7503, the following definitions apply.

2.1 tritium surface contamination: Total activity of tritium adsorbed upon and absorbed into the surface.

2.2 directly measurable tritium surface contamination: Fraction of the tritium surface contamination available for direct measurement.

2.3 removable tritium surface contamination: Fraction of tritium surface contamination which is removable or transferable under normal working conditions.

NOTES

1 The definition of the term "normal working conditions" is important for the evaluation of inhalation and incorporation risks in connection with surface contamination: it is assumed that under "normal working conditions", the maximum intensity of mechanical action which could bring about the removal of surface contamination is restricted to that of

- normal, non-accidental contacts of the human body (protected or unprotected by clothes) with surfaces, and
- non-destructive contacts of similar intensity between surfaces and parts of equipment being directly handled by men.

The intensity of action in smear testing should correspond to these types of mechanical action. A single smear will not normally remove all removable contamination.

2 It should be noted that:

- a) under external influences of a chemical nature (e.g. moisture, corrosion, etc.) or of a physical nature (e.g. ambient pressure or temperature changes, vibration, impact, expansion and contraction, etc.), and also as a result of diffusion, the total tritium activity may be transformed into removable contamination;
- b) tritium surface contamination may be volatile or contain volatile fractions which may volatilize under normal working conditions — this also contributes to the removable contamination and should be evaluated appropriately (see also 3.3).

2.4 activity per unit area: Ratio between the tritium surface contamination present and the area of that surface. It is expressed in becquerels centimetres to the power of minus two ($\text{Bq}\cdot\text{cm}^{-2}$).

2.5 indirect evaluation of removable tritium surface contamination: Evaluation of the removable tritium activity on a surface by means of a smear sample.

2.6 smear test: Taking of a sample of removable activity by wiping the surface with dry or wet material and the subsequent evaluation of the activity transferred to the material used to wipe the surface.

NOTE — In most applications, a wet smear has been found preferable for the determination of tritium surface contamination.

2.7 removal factor, F : Ratio of the activity removed from the surface by one smear sample to the activity of the removable surface contamination prior to this sampling (see also ISO 7503-1).

NOTE — For important combinations of contaminant and surface material, the removal factor F can be determined experimentally using the method of "exhaustive removal by repetitive smears". The step-by-step addition of the removed activities results in a good approximation of the total removable activity, to which the activity removed by the first smear can then be related to yield the removal factor.

3 Method for evaluating surface contamination

3.1 General

The problem with the detection of tritium lies in the exceedingly short range of its beta particles, even in air. Tritium, being an

isotope of hydrogen, has great mobility, and, as an unwanted contamination, it may penetrate into a surface to a depth that makes the direct or indirect evaluation of the total tritium surface contamination very difficult.

In many cases, tritium contamination is present in the form of contaminated water, which can evaporate, making the tritium airborne. Indeed, many tritium detection instruments sample air for airborne tritium content. Because of the ability of tritium to diffuse and to be absorbed into the surface and due to the low energy of its beta emission, special care shall be taken when evaluating tritium surface contamination. The total surface contamination cannot be accurately evaluated by direct or indirect methods. Direct measurements are carried out with contamination-measuring instruments which will not respond to all activity absorbed below the surface. Indirect measurements performed by wet smear tests generally provide a reasonable estimate of the removable surface contamination at the time of collection. However, diffusion of tritium contamination absorbed into the surface will tend to replace the removable surface contamination that was partially or totally removed by a decontamination process or by smear tests. Furthermore, a radiological hazard from volatile tritium may still remain. For a better understanding of the actual hazard in special situations, a combination of direct and indirect methods should be used. However, in most circumstances, smear test evaluation is an adequate method of assessing the actual radiological hazard arising from incorporation in the course of contact with surfaces contaminated by tritium.

3.2 Direct measurement of tritium contamination

3.2.1 Measuring instruments

Measuring instruments that directly detect tritium surface contamination may respond to both the removable activity and part of the activity absorbed into the surface. Specially designed windowless detectors, such as proportional and scintillation detectors, are available for direct detection of various forms of tritium surface contamination. Instruments subjecting the surface to a pressure or temperature change by their operation may detect the presence of volatile tritium fractions or diffusion characteristics.

Because of the small distances between detectors and surfaces required for the detection of tritium, the contamination of detectors often causes problems. Spacers or removable masks are used to prevent this.

3.2.2 Requirements to be met by the instruments

The instruments shall be capable of detecting activities below the level of the surface contamination limit, to which the results of the contamination measurements are to be compared (limits set by international or national regulations, or in the absence of such regulations, defined by standards or local consensus).

NOTES

1 Because of the low biological hazard of tritium, allowable levels of surface contamination may be fairly high, as recommended by ICRP Publication 25 which suggests $400 \text{ Bq}\cdot\text{cm}^{-2}$ ⁽¹⁾.

2 For specialized applications where tritium surface contamination has to be kept extremely low, methods are available that can detect down to $0,4 \text{ Bq}\cdot\text{cm}^{-2}$.

3.2.3 Detection procedure

Listening for a change in the frequency of the audio clicks, move the instrument over the surface or place it sequentially in such a way that the operational requirements of distance and gas composition are complied with. The audible indication is instantaneous — irrespective of the response time used. Once a contaminated area is detected, the detector should be positioned over this area and held stationary for a time sufficient to confirm the detection.

If practical, low-activity areas should be checked prior to those of high activity in order to minimize the risk of cross-contamination.

3.2.4 Measurement procedure

When making a measurement, the operating instructions relating to the measuring instruments used and the following requirements shall be complied with:

- the background count rate shall be determined at a place representative of the area to be surveyed (for example at the surface to be checked, which for this purpose, is covered by a clean sheet of paper);
- the background count rate shall be checked frequently, because the detector is liable to become contaminated;
- the correct functioning of the instrument should be verified using a suitable check source. Frequency: daily for instruments in frequent use, otherwise before each use. Deviations of more than 25 % from the agreed value shall give rise to a recalibration of the instrument;
- removable spacers may be required.

3.3 Indirect evaluation of removable surface contamination

3.3.1 General

The indirect method is particularly suitable for evaluating the contamination of surfaces which

- do not allow direct measurement (e.g. as a result of configuration, position, etc.), or which
- are located in radiation fields which upset direct measurement, or which
- have overlying material that reduces the intensity of radiation available for direct measurement.

However, the indirect method does not indicate the hazard from volatile tritium fractions present below the surface (see 3.1 and 3.2.1).

3.3.2 Detection limits

Currently available liquid scintillation counters and windowless counters are capable of measuring $0,4 \text{ Bq}$ and 40 Bq , respectively (see the note).