

**Selles, manchons et accessoires pour
travaux sous tension**

**Saddles, pole clamps (stick clamps)
and accessories for live working**

CORRIGENDUM 2

Page 8

1.2 Références normatives

Supprimer:

CEI 410:1973, *Plans et règles d'échantillonnage pour les contrôles par attributs*

Ajouter les publications suivantes:

CEI 61318:1994, *Travaux sous tension – Guide pour les plans d'assurance de la qualité*

ISO 2859-1:1999, *Règles d'échantillonnage pour les contrôles par attributs – Partie 1: Procédures d'échantillonnage pour les contrôles lot par lot, indexés d'après le niveau de qualité acceptable (NQA)*

1.3.1 Termes définis selon les CEI 50(151) et CEI 410

Au lieu de:

... et CEI 410

lire:

... et CEI 61318

Page 10

1.3.1.6 défaut mineur

Au lieu de:

(voir 2.1.3, CEI 410).

lire:

(voir 2.6 de la CEI 61318).

Page 9

1.2 Normative references

Delete:

IEC 410:1973, *Sampling plans and procedures for inspection by attributes*

Add the following publications:

IEC 61318:1994, *Live working – Guidelines for quality assurance plans*

ISO 2859-1:1999, *Sampling procedures for inspection by attributes – Part 1: Sampling schemes indexed by acceptance quality limit (AQL) for lot-by-lot inspection*

1.3.1 Terms defined in accordance with IEC 50(151) and IEC 410

Instead of:

... and IEC 410

read:

... and IEC 61318

Page 11

1.3.1.6 minor defect

Instead of:

(see 2.1.3, IEC 410).

read:

(see 2.6 of IEC 61318).