

S A E
AEROSPACE INFORMATION
REPORT
NO. 32B

COCKPIT VISIBILITY
FOR
COMMERCIAL TRANSPORT AIRCRAFT



② INACTIVE FOR NEW DESIGN OF CIVIL TYPE TRANSPORTS,
EFFECTIVE JUNE 1, 1960, SEE AS 580

MARCH 1, 1964

PREPARED BY

Committee S-7, Flight Deck and Handling
Qualities Standards

SOCIETY OF AUTOMOTIVE ENGINEERS, INC.
485 Lexington Avenue, New York 17, N. Y.

SAENORM.COM : Click to view the full PDF of air32b

Section 8.3 of the SAE Technical Board rules provides that: "All technical reports, including standards approved and practices recommended, are advisory only. Their use by anyone engaged in industry or trade is entirely voluntary. There is no agreement to adhere to any SAE standard or recommended practice, and no commitment to conform to or be guided by any technical report. In formulating and approving technical reports, the Board and its Committees will not investigate or consider patents which may apply to the subject matter. Prospective users of the report are responsible for protecting themselves against liability for infringement of patents."

COCKPIT VISIBILITY FOR COMMERCIAL TRANSPORT AIRCRAFT

INTRODUCTION

This report is intended to encourage more effort to be directed toward improving the pilot's visibility from the cockpit of transport type aircraft with the ultimate objective of improving safety.

In the preparation of this Aeronautical Information Report, consideration was given to pilot surveys made by the Civil Aeronautics Administration, studies made by manufacturers, and a review of the cockpit visibility provided in present day transport aircraft.

It is recognized that a rigid specification is undesirable and may restrict development and utilization of initiative. For this reason the report is in general terms and offered as a guide.

SOCIETY OF AUTOMOTIVE ENGINEERS, Inc.

Committee S-7, Cockpit Standardization*

M. G. Beard, Chairman
American Airlines System
Capt. Scott Flower, Vice-Chairman
Pan American World Airways

Glenn H. Brink
American Airlines System

M. B. Cahill
Northwest Airlines, Inc.

C. M. Christenson
United Air Lines, Inc.

F. E. Davis
Eastern Air Lines, Inc.

John B. Fornasero
Boeing Airplane Co.

Bert Foulds
Douglas Aircraft Co., Inc.

O. R. Hauter
Continental Air Lines

J. B. LeClaire
Transcontinental & Western Air

R. L. Thoren
Lockheed Aircraft Corp.

O. E. Tibbs
Glenn L. Martin Co.

* Committee structure at original publication date.

APPROVED BY SAE AERONAUTICS COMMITTEE

W. C. Lawrence, Chairman
American Airlines

W. B. Bergen
Glenn L. Martin Co.

D. M. McGrath
Bendix Aviation Corp.

G. W. Brady
Curtiss-Wright Corp.

C. E. Mines
Allison Div. - GMC

John C. Buckwalter
Douglas Aircraft Co.

Arthur Nutt
Bridgeport-Lycoming

J. B. Johnson
USAF Air Development Center

C. L. Sadler
Sundstrand Machine Tool Co.

R. D. Kelly
United Air Lines, Inc.

A. E. Smith
Pratt & Whitney Aircraft

SAENORM.COM : Click to view the full PDF of air32b