

Society of Automotive Engineers, Inc.
29 West 39th Street
New York City


AERONAUTICAL RECOMMENDED PRACTICE

ARP 381

HUB, FLANGED - SPLINE TYPE WOOD PROPELLER - #10, #20

Issued 2-1-49
Revised

INACTIVE FOR NEW DESIGN



Section 7C of the SAE Technical Board rules provides that: "All technical reports including standards approved and practices recommended, are advisory only. Their use by anyone engaged in industry or trade is entirely voluntary. There is no agreement to adhere to any SAE standard or recommended practice, and no commitment to conform to or be guided by any technical report. In formulating and approving technical reports, the Board and its Committees will not investigate or consider patents which may apply to the subject matter. Prospective users of the report are responsible for protecting themselves against infringement of patents."