



INTERNATIONAL STANDARD ISO 14695:2003
TECHNICAL CORRIGENDUM 1

Published 2009-03-01

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION • МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ • ORGANISATION INTERNATIONALE DE NORMALISATION

Industrial fans — Method of measurement of fan vibration

TECHNICAL CORRIGENDUM 1

Ventilateurs industriels — Méthode de mesure des vibrations des ventilateurs

RECTIFICATIF TECHNIQUE 1

Technical Corrigendum 1 to ISO 14695:2003 was prepared by Technical Committee ISO/TC 117, *Fans*.

Page 1, Normative references

Replace the references to ISO 1940-1, ISO 5801 and ISO 14694, respectively with the following:

ISO 1940-1, *Mechanical vibration — Balance quality requirements for rotors in a constant (rigid) state — Part 1: Specification and verification of balance tolerances*

ISO 5801:2007, *Industrial fans — Performance testing using standardized airways*

ISO 14694:2003, *Industrial fans — Specifications for balance quality and vibration levels*

Page 6, Figure 1, Note

Replace the third sentence of the note with the following:

This figure is generally in accordance with Figure 44 a) of ISO 5801:2007 with the addition of a flexible connection and resilient mounts between the fan and ducting.