



Methods for the calibration of vibration and shock pick-ups —

Part 0: Basic concepts

TECHNICAL CORRIGENDUM 1

Méthodes pour l'étalonnage des capteurs de vibrations et de chocs —

Partie 0: Concepts de base

RECTIFICATIF TECHNIQUE 1

Technical corrigendum 1 to International Standard ISO 5347-0:1987 was prepared by Technical Committee ISO/TC 108, *Mechanical vibration and shock*, Sub-Committee SC 3, *Use and calibration of vibration and shock measuring instruments*.

Page 7

Subclause 6.2.2

Second paragraph, lines 3 and 4, delete "in the velocity-sensing coil" and insert "generated by the accelerometer".

Second paragraph, line 5, delete "surface of the mounting table" and insert "mounting surface".

Page 9

Subclause 6.2.2

Third paragraph, line 7, delete "per metre".